

U.S TUUMAT JA METRISET

U.S tuuma	U.S tuuma desimaaleina	Metriten mm
1/64	0,015625	0,39688
1/32	0,031250	0,79375
3/64	0,046875	1,19063
1/16	0,062500	1,58750
5/64	0,078125	1,98438
3/32	0,093750	2,38125
7/64	0,109375	2,77813
1/8	0,125000	3,17500
9/64	0,140625	3,57188
5/32	0,156250	3,96875
11/64	0,171875	4,36563
3/16	0,187500	4,76250
13/64	0,203125	5,15938
7/32	0,218750	5,55625
15/64	0,234375	5,95313
1/4	0,250000	6,35000
17/64	0,265625	6,74688
9/32	0,281250	7,14375
19/64	0,296875	7,54063
5/16	0,312500	7,93750
21/64	0,328125	8,33438
11/32	0,343750	8,73125
23/64	0,359375	9,12813
3/8	0,375000	9,52500
25/64	0,390625	9,92188
13/32	0,406250	10,31875
27/64	0,421875	10,71563
7/16	0,437500	11,11250
29/64	0,453125	11,50938
15/32	0,468750	11,90625
31/64	0,484375	12,30313
1/2	0,500000	12,70000
33/64	0,515625	13,09688
17/32	0,531250	13,49375
35/64	0,546875	13,89063
9/16	0,562500	14,28750
37/64	0,578125	14,68438
19/32	0,593750	15,08125
39/64	0,609375	15,47813
5/8	0,625000	15,87500
41/64	0,640625	16,27188
21/32	0,656250	16,66875
43/64	0,671875	17,06563
11/16	0,687500	17,46250
45/64	0,703125	17,85938
23/32	0,718750	18,25625
47/64	0,734375	18,65313
3/4	0,750000	19,05000
49/64	0,765625	19,44688
25/32	0,781250	19,84375
51/64	0,796875	20,24063
13/16	0,812500	20,63750
53/64	0,828125	21,03438
27/32	0,843750	21,43125
55/64	0,859375	21,82813
7/8	0,875000	22,22500
57/64	0,890625	22,62188
29/32	0,906250	23,01875
59/64	0,921875	23,41563
15/16	0,937500	23,81250
61/64	0,953125	24,20938
31/32	0,968750	24,60625
63/64	0,984375	25,00313
1	1,000000	25,40000